




93202 – ACCESSORY RACK

(FOR 93201 AND 93450 BOXES)



Hardware Pack Includes:

- 1 – RACK WELDMENT
- 4 – ¼” – 20 X 1” TRUSS HEAD BOLT
- 4 – ¼” – 20 WASHERS

INSTRUCTIONS –

1. USING A ¼” DRILL BIT, DRILL THE BOX FROM THE BOTTOM SIDE OF THE LID. THERE ARE KISS OFFS MOLDED IN THE LID THAT WILL SHOW YOU WHERE YOU NEED TO DRILL. DUE TO THE TOLERANCE IN THE PLASTIC AND THE WELDING PROCESS SOME HOLES MAY NEED TO BE OVERSIZED TO ALLOW BETTER FITMENT OF THE RACK.
2. PLACE THE WASHER ONTO THE ¼” X 1.00” TRUSS HEAD.
3. THREAD ALL 4 LOOSELY INTO THE “FEET” OF THE RACK. THIS WILL ALLOW YOU TO MOVE AND ADJUST THE RACK TO FIT THE HOLE PATTERNS AS NEEDED. ONCE ALL 4 ARE STARTED, YOU MAY TIGHTEN THE RACK SECURELY.
4. CLEAR OR BLACK SILICONE CAN BE ADDED TO THE CONNECTION BETWEEN THE FEET AND THE TOP OF THE LID TO HELP SEAL OUT WATER.
5. BE SURE TO CHECK THE HARDWARE PERIODICALLY TO ENSURE PROPER TENSION.



93202 RACK SHOWN ON 93201 BOX